

## **Corpus Christi Church**

CONSTRUCTION UPDATE | February 26th, 2021 REPORT NO.: 38

## **Completed Activities**

- Completed Punchlist walkthrough
- Completed final trade inspections



NAVE PEWS AND WINDOWS FACING SOUTHEAST



DJ OVERLOOKING AND SINGING FROM THE CHOIR LOFT



SUBSTANTIAL COMPLETION | March 2021



CHOIR LOFT AND ROSE WINDOW

## **Critical Issues and Pending Approvals**

Final Inspections and Substantial Completion

## **Look Ahead Schedule**

- Final building inspection
- Substantial Completion
- Complete Punchlist
- Owner liturgical furnishings





SUNSET AT THE CHOIR LOFT



VIEW FROM NORTHWEST CORNER